



SITE: IDEAL COOPERAGE  
DATE: JUNE 10-20, 1991  
PHOTOS BY: P. DI PASCA (TAT)  
DESCRIPTION: FINAL DAYS OF  
SITE ACTIVITY



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - northern  
area of site



3405-1K  
NJA0975009

HAZARDOUS  
WASTE



HAZARDOUS  
WASTE

NJA0975009  
3405-1K



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 10, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: 2 drums of flammable liquid  
to be shipped to Cycle Chem



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 10, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Consolidation of drum  
fragments



SITE: Ideal Cooperage, Jersey City, NJ  
DATE: June 10, 1991  
PHOTO BY: P. Di Pasca, Weston TAT  
DESCRIPTION: Consolidation of drum  
                  fragments



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 10, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Shipment of 2 flammable  
liquid drums to Cycle Chem





SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 10, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Consolidation of drum  
fragments



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 10, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Consolidation of drum  
fragments



3405-1K  
340975009

HAZARDOUS  
MATERIAL



HAZARDOUS  
MATERIAL



NJA0975009  
340905-1K



SITE: Ideal Cooperage, Jersey City, NJ  
DATE: June 10, 1991  
PHOTO BY: P. Di Pasca, Weston TAT  
DESCRIPTION: 2 drums of flammable liquid  
to be shipped to Cycle Chem







SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 10, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Shipment of 2 flammable  
liquid drums to Cycle Chem



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 11, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Loading of empty drums for  
shipment to Cardinal Comp.



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 11, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Loading of empty drums for  
shipment to Cardinal Comp.



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 11, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Central area of site during  
loading of empty drums





SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 11, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Loading of empty drums for  
shipment to Cardinal Comp.



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 11, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Loading of empty drums for  
shipment to Cardinal Comp.



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 11, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Loading of empty drums for  
shipment to Cardinal Comp.





SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 11, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Loading of empty drums for  
shipment to Cardinal Comp.



SITE: Ideal Cooperage, Jersey City, NJ  
DATE: June 11, 1991  
PHOTO BY: P. Di Pasca, Weston TAT  
DESCRIPTION: Central area of site during  
loading of empty drums



SITE: Ideal Cooperage, Jersey City, NJ  
DATE: June 20, 1991  
PHOTO BY: P. Di Pasca, Weston TAT  
DESCRIPTION: Final restaging area for  
full drums



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Stray tar solids drum  
discovered under pile of  
empty polyethylene drums





SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - central  
area of site



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - southern  
area of site



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - southern  
area of site







SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - northern  
area of site



SITE: Ideal Cooperage, Jersey City, NJ  
DATE: June 20, 1991  
PHOTO BY: P. Di Pasca, Weston TAT  
DESCRIPTION: Site condition at completion  
of removal action - southern  
area of site



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - northern  
area of site



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - western  
area of site





SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - southern  
area of site



SITE: Ideal Cooperage, Jersey City, NJ  
DATE: June 20, 1991  
PHOTO BY: P. Di Pasca, Weston TAT  
DESCRIPTION: Final restaging area for  
full drums





SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Stray tar solids drum  
discovered under pile of  
empty polyethylene drums





SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - central  
area of site



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - southern  
area of site



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - central  
area of site



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - northern  
area of site





SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - western  
area of site



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - southern  
area of site



SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - southern  
area of site







SITE: Ideal Cooperage, Jersey City, NJ

DATE: June 20, 1991

PHOTO BY: P. Di Pasca, Weston TAT

DESCRIPTION: Site condition at completion  
of removal action - southern  
area of site